CERTIFICATE OF ANALYSIS

Milbank Manufacturing Company

1400 E. Havens P.O. Box 754

Kokomo, IN 46903-0754 Attn: Ronda S. Yeakley

Purchase Order: 206941

Invoice Number:

Order #: 98-02-458

Date: 02/18/98 14:22

Work ID: Effluent Water Composite

Date Received: 02/16/98 Date Completed: 02/18/98

Client Code: MILBANK MFG

SAMPLE IDENTIFICATION

Sample

Sample

Number

Description

Effluent Water Composite

Sample

Sample

Number

Description

This report may not be reproduced except in full, without the written approval of the laboratory. All results relate only

to the items tested.

This report contains a total number of pages;

Order # 98-02-458 02/18/98 14:22


TEST RESULTS BY SAMPLE

Sample: 01AW Effluent Water Composite Collected: 02/13/98 Category: WATER

Test Description Zinc, ICAPES

Result 9.160 <u>Limit</u> 0.010

<u>Units</u> <u>Analyzed</u> <u>By</u> mg/L 02/18/98 JAR







ESG Soratories

5933 West 71st Street * Indianapolis, IN 46278 Phone (317) 290-1471 * Fax (317) 290-1670

CHAIN OF CUSTODY RECORD

Client Name: Project No: Sampler(s) Signature: Stat.No DATE TIME			dila			Total Number of Containers	Filtered (Y or N) Preserv. Code Analyses					 		7	/	Comments	Preservation Codes: A = Acld B = Base C = Cool 4°
	2-13.55	7023°°	_		Effluent Pit	114	1					*					
					1							***					
					()												
													ý				
					, in the second								<u></u>				
					, '												
												w)					
								· **	n).				-				
														-			
						-				-							
						-											
				,		+											
Relinquished By: Relinquished By: Relinquished By:			Date / Time Received By: Date / Time Received By: Date / Time Received By:				Turn Around Time: Normal Rush Report Due: Are samples suspected to be: Flammable Corrosive Toxic Were samples received intact and properly preserved? Yes No										